



SERVICE BULLETIN 2005    DATE 8/1/67    REVISIONS None

APPROVAL: DER

- I. SUBJECT: Main Gear Inboard Door Spring
- II. PURPOSE: To increase the service life of the door opening spring.
- III. EFFECTIVITY: Meyers Model 200, Serial #251 to 298, inclusive.  
Aero Commander Model 200, Serial #301 to 383, inclusive.
- IV. COMPLIANCE: As soon as possible, but not later than next periodic.
- V. REFERENCE DATA: Aero Commander Drawing SB 2005-1
- VI. PROCEDURE: Install Service Kit SB 2005
  1. Place aircraft on jacks.
  2. Retract gear sufficiently to allow the inboard main gear doors to come fully open.
  3. Remove present springs and all attaching hardware.
  4. Install new springs and attaching hardware as per drawing SB 2005-1.

NOTE: On some earlier aircraft, the hole in the wing may have to be enlarged (#10 drill) to accept the screw attaching the O/B link (61C183-3) to the structure.

5. After installation check freefall extension of gear as outlined in Aero Commander Service Bulletin SB 2004.
6. Make log book entry, noting compliance with Aero Commander Service Bulletin SB 2005.
7. Fill our compliance card and return to Aero Commander, Albany Division.

Page Two

8. This kit is furnished free of charge, and should be ordered from:

Aero Commander, Inc.  
Albany Division  
P. O. Box 288  
Albany, Georgia 31702  
Attn: Service Parts Department

The following information must be included with the order:

1. Owner's Name and Address
2. Aircraft Serial Number
3. Address where parts are to be shipped
4. Request Service Kit SB 2005.



Robert L. Frank  
Manager  
Parts & Service Operations

Prepared	NAME <i>R. Stephens</i>	DATE <i>2-18-67</i>	AERO COMMANDER INC. ALBANY, GEORGIA	Page	TEMP.	PERM.
Checked			TITLE SB 2005-1	Model	200	
Approved	<i>R. Stephens</i>	2-18-67		Report No.		

